




Drawing



How To Order

Example

Basic Model

Type

S : Standard (Without Priming) Range upto 700 bar **H** : Heavy Duty (With Priming Pump) Range 700 bar to 2000 bar

Range

100 100 bar	700 700 bar	202 2000bar
200 200 bar	101 1000 bar	
400 400 bar	105 1500 bar	

CT1

X

XXX

Ordering Example : CT1. X . XXX

Note : Specifications and dimensions given in this product catalogue represents the state of engineering at the time of printing.

Modifications may take place and materials specified may be replaced by others without prior notice.

For Any Custom / Non Standard / Special Requirement Consult Factory..

Gauges Shown in Image is not part of standard equipment, For Understanding Only.